

PART 1 GENERAL**1.01 SECTION INCLUDES**

- A. Manually-operated window shades and accessories for sun/glare/heat control and room darkening.

1.02 SUBMITTALS

- A. See Section 01 3000 - Administrative Requirements, for submittal procedures.
- B. Product Data: Manufacturer's catalog data, product descriptions, installation instructions, detail sheets, and specifications for each type system specified.
- C. Shop Drawings: Prepared specifically for this project; show dimensions and interface with other products.
 - 1. Room schedule including field-verified dimensions of each opening to receive window shade systems.
 - 2. Indicate System Series, operator, fabric selection, and mounting type.
 - 3. Indicate control type.

1.03 QUALITY ASSURANCE

- A. Installer: Approved by manufacturer.

1.04 DELIVERY, STORAGE, AND HANDLING

- A. Deliver products to project site in manufacturer's original cartons.
- B. Individually package and mark shades with room number and opening number.
- C. Inspect the materials upon delivery to assure that specified products have been received.
- D. Store and handle shades to prevent damage to fabrics, finishes, and operators prior to installation.

PART 2 PRODUCTS**2.01 MANUFACTURERS**

- A. Acceptable Manufacturer: Shade Techniques, Inc; P.O. Box 608, 4191 E. Gregory Road, Eaton, IN 47338; ASD. Tel: (765) 396-9903, Fax: (765) 396-9904.
- B. Acceptable Manufacturer: MechoShade Systems, Inc.; 42-03 35th Street, Long Island City, NY 11101. ASD. Tel: (718) 729-2020. Fax: (718) 729-2941.
- C. Provide all window shade systems from a single manufacturer.

2.02 MANUFACTURED UNITS

- A. Manually-operated Shades: MechoShade Systems, Inc.; Product "Mecho/5".
 - 1. Shadecloth:
 - a. As specified in Section 09000 Interior Finish Specifications.

2.03 COMPONENTS

- A. Mounting Brackets: Stamped steel, custom fabricated as required for ceiling mounting.

PART 3 EXECUTION**3.01 INSTALLATION**

- A. Install window shade systems in accordance with manufacturer's instructions and these specifications.
- B. Assume responsibility for all field dimensions and mounting surfaces.
- C. Adjust window shade systems for proper operation.

END OF SECTION